

Your Guarantee Certificate

Conditions for Legno Bastone guarantee.

Legno Bastone is only responsible for manufacturing faults. This guarantee is valid for 25 years from the moment of purchase. The invoice date is proof of purchase date. The appearance of color changes, the occurrence of openings and/or open seams, surface variations and malformations, for example from ageing of the floor, climatic changes or use, are not covered by this guarantee. The Legno Bastone floor must be correctly installed according to the provided installation instructions. The guarantee covers normal use of the floor but is null and void if the floor is installed in damp or humid spaces. Floor components that show visible abnormalities should not be installed. Floor components that are installed despite visible defects do not fall under the guarantee. Multilayer parquet is liable to normal wear and tear not covered by this guarantee. Only abnormal wear is covered by the guarantee. Exclusions: scratches, dents from heavy objects, damp damage as a result of unsuitable use, maintenance or accidents. If you believe there is a defect that falls under this guarantee, you must inform your dealer within 15 days of the discovery of the defect. The guarantee given is only valid for the floor components supplied. This means that the manufacture cannot be held liable for labor costs, man-hours, the cost of additional materials or other loss incurred. Should a dispute arise about the Legno Bastone guarantee, each party can appoint an independent expert to offer binding advice concerning the floor components supplied. If this clause has to be invoked, the cost price of such expertise shall be agreed in writing and in advance between the parties involved. Any causes of damage and/or damagecausing components must be kept and made available to Legno Bastone if required. The guarantee period will not be changed once a complaint has been recognized and resolved. If the guarantee is applicable, Legno Bastone will resupply the defective floor components or offer compensation. If the product in question is no longer available, Legno Bastone guarantees that it will be replaced by an alternative product of the same quality. Legno Bastone must in any case be given the opportunity to repair the arising damage itself in a manner of its choosing or have it done by a third party. In the event of a complaint, the beneficiary shall prove that at the moment of initial use of the product, the assembly and installation was carried out according to professional standards and was accepted by him without reservation. At the request of Legno Bastone, all documents concerning the initial use (such as order confirmations, invoices, installation plans, etc.) will be submitted to Legno Bastone.

The guarantee is not valid in the following cases:

The floor is not installed according to the Legno Bastone installation instructions. The defects were visible before the floor was installed. The problems are the result of humidity or water damage or other causes resulting from force majeure. The defects and/or faults are the result of incorrect usage or careless handling and use for another purpose than intended, as well as ignoring maintenance instructions or warnings. Optical faults resulting from the malformation of the panels by altered climatic conditions, in case of color changes due to the effect of sunlight and the consequences of normal ageing and/or wear and tear of the top layer. Stains or mechanical damage on the surface (dents, scratches, etc.) arising from careless treatment during transport, storage, and in case of damage as a result of stiletto heels, furniture, stones, sand, pets, etc. In the case of under floor heating, whereby shakes/cracks appear on the surface face of the board, this is a result of consistent heating over the desired range (15-27c) and/or a sudden increase in the temperature settings of the under floor heating system. As such incidences are outside the control of Legno Bastone we cannot guarantee against such issues if they arise. Warranty is also null and void unless strict adherence to supplied maintenance and care instructions and schedule are followed

2684 Horseshoe Drive South Naples, Florida 34104 P: 239-206-1898 F: 239-262-1689 Info@LegnoBastone.com